

<b>Storage temperature / humidity</b>	-20 to 700C, 70% RH max
<b>Operating temperature / humidity</b>	-10 to 500C, 70% RH max
<b>Pollution degree</b>	2
<b>DC Voltage</b>	0 to +70 Volts +1 digit
<b>P-P Voltage</b>	0 to +70 Volts
<b>Frequency Response</b>	10Hz to 10kHz (for tone pass through)
<b>P-P display</b>	15Hz Square Wave / 35Hz Sine Wave
<b>DC Voltmeter Mode - Continuity to ground</b>	
<ul style="list-style-type: none"> <li>- First Level - display is enabled less than 20K <math>\Omega</math></li> <li>- Second Level green LED is enabled less than approx. 650 <math>\Omega</math></li> <li>- + Peak Detector Response</li> <li>- Single event capture less than 200mS pulse width</li> <li>- Repetitive events less than 1mS pulse width</li> <li>- Peak to Peak Mode ..... 0 to +70 Volts + 1 digit</li> <li>- 4Hz to over 500kHz Square Wave input</li> <li>- 4Hz to over 250kHz Sine Wave input</li> </ul>	
<b>Over Volt Warning</b>	
<p>If the probe tip connects to a voltage greater than +70 Volts the display will show an "Over Volt" warning.</p> <p>Remove the probe tip immediately to prevent internal damage to the tool.</p>	
<b>Over Load Warning</b>	

If the probe is connected to a battery with voltage greater than 34VDC the display will show an "Over Load" warning.