


TECHINICAL SPECIFICATION	ETAD-E2430	COUNT	REVISIONS	BY	CHKD	DATE
TITLE						
TM21P-TM-88P						
CABLING MANUAL						
[APPLICABLE :OKI ELECTRIC CABLE CO LTD 0.5 4P F-DTI-CS(SLA)]						

1. APPLICATION

THIS DOCUMENT DEFINES CABLE ASSEMBLY METHOD FOR TM21P-TM-88P.
THIS CABLE ASSEMBLY METHOD IS FOR HIROSE APPROVED CABLE.

MANUFACTURE	OKI ELECTRIC CABLE CO LTD
PRODUCT NAME	0.5 4P F-DTI-CT(SLA)
CONDUCTOR SIZE	φ 0.5mm SOLID WIRE
INSULATION DIAMETER	φ 1mm
GROUND WIRE	AWG#26 (TIN COAT WIRE)
OUTER JACKET DIAMETER	φ 6.5mm



2. PLUG WIRING TOOL




	TOOL NAME	TOOL CL NO.
IDC HAND TOOL	*HIROSE ELECTRIC GmbH HAND TOOL	-
CABLE CLAMPING HAND TOOL	HT206/TM21P-88P	CL250-0235-7



*DO NOT USE IDC HAND TOOL (HT205/TM21P-88P) MAED FROM HIROSE ELECTRIC CO.,LTD






TO
Q

	WRITTEN	DESIGNED	REVIEWED	APPROVED	RELEASED
	<i>S. Sato</i> 04.11.04	<i>S. Sato</i> 04.11.04	<i>H. Miura</i> 04.11.04	<i>H. Miura</i> 04.11.04	

3. CABLE ASSEMBLY METHOD

PROCEDURE	WORK CONTENTS
<p>1. CABLE END TREATMENT</p>	<p>1-1. STRIP OF OUTER JACKET STRIP OUTER JACKET NOT TO CRACK INSULATION CONDUCTOR.</p>  <p>1-2. CUT OF SHILD CUT SHILD BY EDGE OF OUTER JACKET.</p>  <p>1-3. CUT OF POLYETHYLENE TAPE CUT POLYETHYLENE TAPE BY EDGE OF OUTER JACKET.</p> 


<p>2. CORE CABLE FORMING</p>	<p>2-1. DRESS STRAIGHT OF TWISTED PAIR CABLE CORE CABLE TO BE DRESSED STRAIGHT WITH NO BUDGE TO END OF OUTER JACKET. GROUND WIRE MUST BE FOLDED AS SHOWN.</p>  <p>2-2. SPRED CORE CABLE SPREAD CORE CABLE ACCORDING TO CONNECTOR PIN ASSIGNMENT.</p> 
------------------------------	---

PROCEDURE	WORK CONTENTS
<p>3. CABLE ARRANGEMENT</p>	<p>3-1. ARRANGEMENT OF CORE CABLE ARRANGE CORE CABLE ACCORDING TO CONNECTOR PIN ASSIGNMENT.</p>  <p>3-2. DRESS ALL EXCESS CORE CABLE (1) DRESS ALL EXCESS CORE CABLE. EASY INSTALL GUIDE PLATE.</p>  <p>CUT OF CORE CABLE</p> <p>3-3. INSTALL GUIDE PLATE INSTALL GUIDE PLATE WITH A CLEARANCE OF 3~5mm FROM THE END OF OUTER JACKET. SHOULD BE NO DEFORMATION OF GUIDE PLATE.</p>  <p>GUIDE PLATE</p> <p>3~5mm</p>  <p>DEFORMATION OF GUIDE PLATE</p>
<p>4. CABLE AND TREATMENT (2)</p>	<p>4-1. STRIP OUTER JACKET STRIP OUTER JACKET WITH A CLEARANCE OF 14 ± 1mm FROM GUIDE PLATE. REMAIN SHILD.</p>  <p>14 ± 1mm</p> <p>SHILD</p>


PROCEDURE

WORK CONTENTS


4-2. COIL COPPER TAPE (1)
 COIL COPPER TAPE (12.7mm WIDTH) ONE TURN.
 THE END OF OUTER JACKET.




4-3. FORMING OF GROUND WIRE
 DRESS GROUND WIRE IS SHOWN.
 CUT EXCESS GROUND WIRE FROM COPPER TAPE.




4-4. COIL COPPER TAPE (2)
 COIL THE REMAIN OF COPPER TAPE.



4-5. THE LENGTH OF COPPER TAPE
 DIAMETER OF COPPER TAPE PORTION SHOULD BE ABOUT 6.8mm.
 EXCEPT GROUND WIRE AREA.
 (REF :L=32mm LENGTH FOR DIAMETER 6.5mm CABLE)





4-6. DRESS ALL EXCESS CORE CABLE (2)
 DRESS ALL EXCESS CORE CABLE WITH A CLEARANCE OF 0.5mm
 FROM TIP TO GUIDE PLATE.




PROCEDURE WORK CONTENTS

5. INSTALL GUIDE PLATE INTO PLUG BODY

INSTALL GUIDE PLATE AS SHOWN SO THAT GUIDE PLATE DOES NOT CONTACT CLAMP PORTION. PUSH GUIDE PLATE INTO BOTTOM SURFACE OF PLUG BODY.



PUSH AND ENSURE CORE CABLE CONTACT WITH BOTTOM SURFACE OF PLUG BODY




PROCEDURE

WORK CONTENTS

6. IDC
TERMINATION


6-1. CAUTION OF IDC TERMINATION

CHECK IF CORE CABLE CONTACT WITH BOTTOM SURFACE OF
PLUG BODY AND ASSEMBLY BY HIROSE GmbH IDC TOOLING.
WHEN ASSEMBLY, PUSH CABLE TIGHT AS SHOWN.



6-2. IDC HEIGHT

IDC HEIGHT SHOULD BE AS SHOWN.

7. CABLE CLAMPING
AND FOLDING
GROUND PLATE

7-1. CABLE CLAMPING


CLAMP BY HIROSE CLAMPING TOOLING.

CABLE CLAMP HEIGHT

C/H : 6.5~6.9mm

CABLE TENSILE FORCE

78.4N (8Kg) MIN



PROCEDURE

WORK CONTENTS

7-2. FOLDING GROUND PLATE
GROUND PLATE TO BE FOLDED AS SHOWN.
FOLDED AT 45 DEGREE OR MORE.

