

## SAM D5x/E5x Family Silicon Errata and Data Sheet Clarification

### SAM D5x/E5x Family Errata

The SAM D5x/E5x family of devices that you have received conform functionally to the current Device Data Sheet (DS60001507A), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in **SAM D5x/E5x Family Silicon Device Identification**. The silicon issues are summarized in the Table of Contents following this section.

The errata described in this document will be addressed in future revisions of the SAM D5x/E5x family silicon.

**Note:** This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current.

**Table 1. SAM D5x/E5x Family Silicon Device Identification**

Part Number	Device Identification (DID[31:0])	Revision (DID.REVISION[3:0])
		A
ATSAME54P19A	0x6184xx01	0x0
ATSAME54P20A	0x6184xx00	
ATSAME54N19A	0x6184xx03	
ATSAME54N20A	0x6184xx02	
ATSAME53N20A	0x6183xx02	
ATSAME53N19A	0x6183xx03	
ATSAME53J18A	0x6183xx06	
ATSAME53J19A	0x6183xx05	
ATSAME53J20A	0x6183xx04	
ATSAME51N19A	0x6181xx01	
ATSAME51N20A	0x6181xx00	
ATSAME51J18A	0x6181xx03	
ATSAME51J19A	0x6181xx02	
ATSAME51J20A	0x6181xx04	
ATSAMD51P20A	0x6006xx00	

## SAM D5x/E5x Family

Part Number	Device Identification (DID[31:0])	Revision (DID.REVISION[3:0])
		A
ATSAMD51P19A	0x6006xx01	
ATSAMD51N19A	0x6006xx03	
ATSAMD51N20A	0x6006xx02	
ATSAMD51J18A	0x6006xx06	
ATSAMD51J19A	0x6006xx05	
ATSAMD51J20A	0x6006xx04	
ATSAMD51G18A	0x6006xx08	
ATSAMD51G19A	0x6006xx07	

Data Sheet clarifications and corrections (if applicable) are located in [Data Sheet Clarifications](#), following the discussion of silicon issues.

**Note:** Refer to the “Device Service Unit” chapter in the current Device Data Sheet (DS60001507A) detailed information on Device Identification and Revision IDs for your specific device.

# Table of Contents

---

SAM D5x/E5x Family Errata.....	1
1. Silicon Errata Issues.....	4
1.1. Analog-to-Digital Converter (ADC).....	4
1.2. Analog Comparator (AC).....	4
1.3. Controller Area Network (CAN).....	5
1.4. Clock Failure Detector (CFD).....	6
1.5. Device.....	7
1.6. Device Service Unit (DSU).....	8
1.7. 48 MHz Digital Frequency-Locked Loop (DFLL48M).....	8
1.8. Digital-to-Analog Converter (DAC).....	9
1.9. Direct Memory Access Controller (DMAC).....	10
1.10. External Interrupt Controller (EIC).....	11
1.11. Fractional Digital Phase-Locked Loop (FDPLL).....	11
1.12. Non-Volatile Memory Controller (NVMCTRL).....	12
1.13. I/O Pin Controller (PORT).....	13
1.14. Serial Communication Interface (SERCOM).....	13
1.15. Timer/Counter (TC).....	15
1.16. Timer/Counter for Control Applications (TCC).....	15
2. Data Sheet Clarifications.....	16
3. Appendix A: Revision History.....	17
The Microchip Web Site.....	18
Customer Change Notification Service.....	18
Customer Support.....	18
Microchip Devices Code Protection Feature.....	18
Legal Notice.....	19
Trademarks.....	19
Quality Management System Certified by DNV.....	20
Worldwide Sales and Service.....	21

## 1. Silicon Errata Issues

The following issues apply to the SAM D5x/E5x Family devices.

### 1.1 Analog-to-Digital Converter (ADC)

#### 1.1.1 ADC

The ADC SYNCBUSY.SWTRIG gets stuck to '1' after wake-up from Standby Sleep mode.

##### Workaround

Ignore the ADC SYNCBUSY.SWTRIG status when waking up from Sleep mode.

##### Affected Silicon Revisions

A							
X							

#### 1.1.2 ADC

ADC TUE/INL/DNL performance is not guaranteed when:

1. Sampling frequency is above 500 ksps AND
2. ADC VREF is different from VDDANA

##### Workaround

None.

##### Affected Silicon Revisions

A							
X							

### 1.2 Analog Comparator (AC)

#### 1.2.1 AC

Enabling Hysteresis (COMPCTRLn.HYSTEN = 0x1) changes the threshold voltage (VTH-), which may result in unexpected behavior of the Analog Comparator.

##### Workaround

None.

##### Affected Silicon Revisions

A							
X							

## 1.3 Controller Area Network (CAN)

### 1.3.1 CAN

Description:

#### Workaround

When edge filtering is activated (CCCR.EFBI = 1), and when the end of the integration phase coincides with a falling edge at the Rx input pin, it may occur that the CAN synchronizes itself incorrectly and does not correctly receive the first bit of the frame. In this case, the CRC will detect that the first bit was received incorrectly, it will rate the received FD frame as faulty, and an error frame will be send.

The issue only occurs when there is a falling edge at the Rx input pin (CAN\_RX) within the last time quantum (tq) before the end of the integration phase. The last time quantum of the integration phase is at the sample point of the 11th recessive bit of the integration phase. When edge filtering is enabled, the bit timing logic of the CAN sees the Rx input signal delayed by the edge filtering. When the integration phase ends, edge filtering is automatically disabled. This affects the reset of the FD CRC registers at the beginning of the frame. The Classical CRC register is not affected, so this issue does not affect the reception of Classical frames.

In CAN communication, the CAN module may enter an integrating state (either by resetting the CCCR.INIT or by protocol exception event) while a frame is active on the bus. In this case, the 11 recessive bits are counted between the acknowledge bit and the following start of frame. All nodes have synchronized at the beginning of the dominant acknowledge bit. This means that the edge of the following start of frame bit cannot fall on the sample point, so the issue does not occur. The issue occurs only when the CAN is by local errors, mis-synchronized with regard to the other nodes.

Glitch filtering as specified in ISO 11898-1:2015 is fully functional.

Edge filtering was introduced for applications where the data bit time is at least two tq (of nominal bit time) long. In that case, edge filtering requires at least two consecutive dominant time quanta before the counter counting the 11 recessive bits for idle detection is restarted. This means edge filtering covers the theoretical case of occasional 1-tq-long dominant spikes on the CAN bus that would delay idle detection. Repeated dominant spikes on the CAN bus would disturb all CAN communication, so the filtering to speed up idle detection would not help network performance.

When this rare event occurs, the CAN sends an error frame and the sender of the affected frame retransmits the frame. When the retransmitted frame is received, the CAN has left the integration phase and the frame will be received correctly. Edge filtering is only applied during the integration phase; it is never used during normal operation. Since the integration phase is very short with respect to "active communication time", the impact on total error frame rate is negligible. The issue has no impact on data integrity.

The CAN enters the integration phase under the following conditions:

- when CCCR.INIT is set to '0' after start-up
- after a protocol exception event (only when CCCR.PXHD = 0)

*Scope:*

The erratum is limited to FD frame reception when edge filtering is active (CCCR.EFBI = '1') and when the end of the integration phase coincides with a falling edge at the Rx input pin.

*Effects:*

The calculated CRC value does not match the CRC value of the received FD frame and the CAN module sends an error frame. After retransmission the frame is received correctly.

Disable edge filtering or wait on retransmission in the event that this rare event occurs.

### Affected Silicon Revisions

A							
X							

## 1.3.2 CAN

When NBTP.NTSEG2 is configured to zero (Phase\_Seg2(N) = 1), and when there is a pending transmission request, a dominant third bit of Intermission may cause the CAN to wrongly transmit the first identifier bit dominant instead of recessive, even if this bit was configured as '1' in the Tx Buffer Element of the CAN module.

### Workaround

A phase buffer segment 2 of length '1' (Phase\_Seg2(N) = 1) is not sufficient to switch to the first identifier bit after the sample point in Intermission where the dominant bit was detected.

The CAN protocol according to ISO 11898-1 defines that a dominant third bit of Intermission causes a pending transmission to be started immediately. The received dominant bit is handled as if the CAN has transmitted a Start-of-Frame (SoF) bit.

The ISO 11898-1 specifies the minimum configuration range for Phase\_Seg2(N) to be 2..8 tq. Therefore, excluding a Phase\_Seg2(N) of '1' will not affect CAN conformance.

### Effects:

In case NBTP.NTSEG2 = 0, it may occur that the CAN transmits the first identifier bit dominant instead of recessive.

Update configuration range of NBTP.NTSEG2 from 0..127 tq to 1..127 tq in the CAN documentation.

### Affected Silicon Revisions

A							
X							

## 1.4 Clock Failure Detector (CFD)

### 1.4.1 CFD

When the CFD is enabled for XOSC/XOSC32K and the oscillator input signal is stuck at 1, the clock failure detection works correctly but the switch to the safe clock will fail.

### Workaround

Two possible workarounds are:

1. If the main clock source itself comes from the XOSC/XOSC32K oscillator, the only workaround is indirect (i.e., using the WDT in firmware and switch to safe clock source in firmware at WDT reset).
2. Otherwise, since the clock failure detection is functional, once the STATUS.CLKFAIL is set and if the STATUS.CLKSW is not set, manually switch to safe clock from firmware by changing

configurations of the generic clock generators that use the XOSC/XOSC32K as a clock source to use another source clock instead.

## Affected Silicon Revisions

A							
X							

## 1.5 Device

### 1.5.1 Device

The internal pull-up of the RESET pin is not functional.

#### Workaround

An external 100K pull-up must be added on the RESET pin.

## Affected Silicon Revisions

A							
X							

### 1.5.2 Device

The detection of a debugger probe may fail if the "BOD33 Disable" fuse is cleared (i.e., BOD33 is enabled).

#### Workaround

To secure the detection of debugger probes, enable BOD33 using the SUPC.BOD33 register instead of the "BOD33 Disable" fuse. The "BOD33 Disable" fuse must be kept set.

## Affected Silicon Revisions

A							
X							

### 1.5.3 Device

VBAT mode is not functional.

#### Workaround

None.

## Affected Silicon Revisions

A							
X							

## 1.5.4 Device

When the internal reference is used with the DAC and ADC, their outputs become non-linear when the operating temperature is less than 0°C.

### Workaround

The internal reference must be used only for positive temperatures (i.e., above 0°C).

### Affected Silicon Revisions

A							
X							

## 1.6 Device Service Unit (DSU)

### 1.6.1 DSU

DSU CRC32 may never complete when targeting NVM memory space while the NVM cache is disabled.

### Workaround

Be sure to always enable the NVM cache when performing a DSU CRC32 request targeting the NVM memory space.

### Affected Silicon Revisions

A							
X							

## 1.7 48 MHz Digital Frequency-Locked Loop (DFLL48M)

### 1.7.1 DFFL48M

If the DFLL48M reaches the maximum or minimum COARSE or FINE calibration values during the locking sequence, an out of bounds interrupt will be generated. These interrupts will be generated even if the final calibration values at DFLL48M lock are not at maximum or minimum, and might therefore be false out of bounds interrupts.

### Workaround

Check that lockbits DFLLCKC and DFLLCKF in the OSCCTRL Interrupt Flag Status and Clear register (INTFLAG) are both set before enabling the DFLL\_OOB interrupt.

### Affected Silicon Revisions

A							
X							

### 1.7.2 DFFL48M

In Close Loop mode, the STATUS.DFLLRDY bit does not rise before lock fine occurs. Therefore, the information about DFLL ready to start Close Loop mode is not available.



**Workaround**

None.

**Affected Silicon Revisions**

A							
X							

**1.7.3 DFFL48M**

If the DFLL is disabled then re-enabled, the DFLLVAL.FINE value is ignored by the DFLL module, which will then start its lock fine process at another frequency.

**Workaround**

Before writing the final configuration in the DFLLCTRLB register, the DFLL must be re-enabled in Open Loop mode to read and rewrite the DFLLVAL register.

- 1- OSCCTRL->DFLLMUL.reg = X; // Write new DFLLMULL configuration
- 2- OSCCTRL.DFLLCTRLB.reg = 0; // Select Open loop configuration
- 3- OSCCTRL.DFLLCTRLA.bit.ENABLE = 1; // Enable DFLL
- 4- OSCCTRL.DFLLVAL.reg = OSCCTRL->DFLLVAL.reg; // Reload DFLLVAL register
- 5- OSCCTRL.DFLLCTRLB.reg = X; // Write final DFLL configuration

**Affected Silicon Revisions**

A							
X							

**1.8 Digital-to-Analog Converter (DAC)**

**1.8.1 DAC**

In differential mode the smoothing of the output signal is not fully functional. Smoothing works normally in differential mode as long as value of two consecutive data are both positive or are both negative. The behavior is incorrect when the data changes from positive to negative or vice versa.

**Workaround**

None.

**Affected Silicon Revisions**

A							
X							

**1.8.2 DAC**

The selection of VDDANA as the DAC reference in DAC.CTRLB.REFSEL is non-functional.

**Workaround**

The VDDANA must be connected externally to a VREF pin and DAC.CTRLB.VREFAU must be selected.

**Affected Silicon Revisions**

A							
X							

**1.8.3 DAC**

No analog compare will be done on Comparator 0 (AC0) when using the DAC on negative input AIN1 and on Comparator 1 (AC1) when using the DAC on negative input AIN3.

**Workaround**

Use the internal VDD scaler.

**Affected Silicon Revisions**

A							
X							

**1.8.4 DAC**

If the interpolation mode is enabled (with filter integrated to the DAC), the last data from the filter is missing, and therefore, the DAC final output value does not correspond to the DAC input value.

Although interrupt events are generated at the end of conversion (EOC), the EOC occurs before the final value from the filter and is of no use in the application.

**Workaround**

None.

**Affected Silicon Revisions**

A							
X							

**1.9 Direct Memory Access Controller (DMAC)**

**1.9.1 DMAC**

When at least one channel using linked descriptors is already active, a channel Fetch Error (FERR) may occur upon enabling a channel with no linked descriptor or the second descriptor (index 1) of the channel being enabled may be fetched by one of the already active channels using linked descriptors. These errors may occur when a channel is being enabled during the link request of another channel and if the channel number of the channel being enabled is lower than the channel already active.

**Workaround**

When enabling a channel while other channels using linked descriptors are already active, the channel number of the new channel to enable must be greater than the other channel numbers.

## Affected Silicon Revisions

A							
X							

## 1.10 External Interrupt Controller (EIC)

### 1.10.1 EIC

When enabling EIC, SYNCBUSY.ENABLE is released before EIC is fully enabled. Edge detection can be done only after three cycles of the selected GCLK (GCLK\_EIC or CLK\_ULP32K).

#### Workaround

None.

## Affected Silicon Revisions

A							
X							

### 1.10.2 EIC

When the asynchronous edge detection is enabled, and the system is in Standby mode, only the first edge will be detected. The following edges are ignored until the system wakes up.

#### Workaround

Use the asynchronous edge detection with debouncer enabled. It is recommended to set the DPRESALER.PRESALER and DPRESALER.TICKON to have the lowest frequency possible. To reduce the power consumption, set the EIC GCLK frequency as low as possible or select the ULP32K clock (EIC CTRLA.CKSEL set).

## Affected Silicon Revisions

A							
X							

## 1.11 Fractional Digital Phase-Locked Loop (FDPLL)

### 1.11.1 FDPLL

When using a low frequency input clock on FDPLLn, several FDPLL unlocks may occur while the output frequency is stable.

#### Workaround

When using a low frequency input clock on FDPLLn, enable the lock bypass feature to avoid FDPLL unlocks.

## Affected Silicon Revisions

A							
X							

### 1.11.2 FDPLL

When changing the FDPLL ratio in DPLLnRATIO register on-the-fly, STATUS.DPLLnLDRTO will not be set when the ratio update will be completed.

#### Workaround

Wait for the interruption flag INTFLAG.DPLLnLDRTO instead.

## Affected Silicon Revisions

A							
X							

## 1.12 Non-Volatile Memory Controller (NVMCTRL)

### 1.12.1 NVMCTRL

NVM reads may be corrupted when mixing NVM reads with Page Buffer writes.

#### Workaround

Disable cache lines before writing to the Page Buffer when executing from NVM or reading data from NVM while writing to the Page Buffer. Cache lines are disabled by writing a one to CTRLA.CACHEDIS0 and CTRLA.CACHEDIS1.

## Affected Silicon Revisions

A							
X							

### 1.12.2 NVMCTRL

The device does not start correctly under temperatures below -20°C.

#### Workaround

Reset the device (RESET pin) during power-up until VDDIO has reached 2V.

A							
X							

### 1.12.3 NVMCTRL

Flash Write/Erase operations are not functional under temperatures below -20°C.

#### Workaround

VDDIO must be supplied at 2V minimum to guarantee Flash Write/Erase operations down to -40°C .

A							
X							

## 1.13 I/O Pin Controller (PORT)

### 1.13.1 PORT

PORT read/write attempts on non-implemented registers, including addresses beyond the last implemented register group (PA, PB,...), do not generate a PAC protection error.

#### Workaround

None.

#### Affected Silicon Revisions

A							
X							

### 1.13.2 PORT Pull-Up/Pull-Down Resistor

The pull-down on PA24/PA25 are activated during power-up and when Sleep mode is OFF. On all other pins, except those in the VSWOUT cluster, the pull-up is activated during power-up and when Sleep mode is OFF.

#### Workaround

None.

#### Affected Silicon Revisions

A							
X							

## 1.14 Serial Communication Interface (SERCOM)

### 1.14.1 SERCOM

In USART Auto-baud mode, missing stop bits are not recognized as inconsistent sync (ISF) or framing (FERR) errors.

#### Workaround

None.

#### Affected Silicon Revisions

A							
X							

## 1.14.2 SERCOM-I2C

SDAHOLD timing of the SERCOM-I2C does not match the value shown in the current device data sheet. The following table shows the specified and real values of SDA Hold timing.

**Table -1. SDA Hold Timing**

SDA Hold Time Value	Specified SDA Hold Time	Real SDA Hold Time
0x0	Disabled	Disabled
0x1	50 ns to 100 ns	20 ns to 40 ns
0x2	300 ns to 600 ns	100 ns to 250 ns
0x3	400 ns to 800 ns	150 ns to 350 ns

### Workaround

None.

### Affected Silicon Revisions

A							
X							

## 1.14.3 SERCOM

When the 32-bit Extension mode is enabled and Data to be sent is not in multiples of 4 bytes (which means the length counter must be enabled), additional byte(s) will be sent over the line.

### Workarounds

Use either of the following two workarounds:

1. Write the Inter-Character Spacing bits (CTRLC.ICSPACE) to a non-zero-value.
2. Do not use length counter in firmware by keeping data to be sent is in multiples of 4 bytes.

### Affected Silicon Revisions

A							
X							

## 1.14.4 SERCOM-UART

The TXINV and RXINV bits in the CTRLA register have inverted functionality.

### Workarounds

In software, interpret the TXINV bit as a functionality of RXINV, and conversely, interpret the RXINV bit as a functionality of TXINV.

### Affected Silicon Revisions

A							
X							

## 1.15 Timer/Counter (TC)

### 1.15.1 TC

When clearing the STATUS.PERBUFV / STATUS.CCBUFx flag, SYNCBUSY flag is released before the PERBUF / CCBUFx register is restored to its appropriate value.

#### Workaround

Clear successively twice the STATUS.PERBUFV / STATUS.CCBUFx flag to ensure that the PERBUF / CCBUFx register value is properly restored before updating it.

#### Affected Silicon Revisions

A							
X							

## 1.16 Timer/Counter for Control Applications (TCC)

### 1.16.1 TCC

Using TCC in Dithering mode with external retrigger events can lead to an unexpected stretch of right-aligned pulses, or shrink of left-aligned pulses.

#### Workaround

Do not use retrigger events/actions when the TCC module is configured in Dithering mode.

#### Affected Silicon Revisions

A							
X							

## 2. Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (DS60001507A):

**Note:** Corrections in tables, registers, and text are shown in **bold**. Where possible, the original bold text formatting has been removed for clarity.

No clarifications to report at this time.



## 3. Appendix A: Revision History

### Rev A Document (7/2017)

Initial release of this document.

## The Microchip Web Site

---

Microchip provides online support via our web site at <http://www.microchip.com/>. This web site is used as a means to make files and information easily available to customers. Accessible by using your favorite Internet browser, the web site contains the following information:

- **Product Support** – Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- **General Technical Support** – Frequently Asked Questions (FAQ), technical support requests, online discussion groups, Microchip consultant program member listing
- **Business of Microchip** – Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

## Customer Change Notification Service

---

Microchip's customer notification service helps keep customers current on Microchip products. Subscribers will receive e-mail notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, access the Microchip web site at <http://www.microchip.com/>. Under "Support", click on "Customer Change Notification" and follow the registration instructions.

## Customer Support

---

Users of Microchip products can receive assistance through several channels:

- Distributor or Representative
- Local Sales Office
- Field Application Engineer (FAE)
- Technical Support

Customers should contact their distributor, representative or Field Application Engineer (FAE) for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in the back of this document.

Technical support is available through the web site at: <http://www.microchip.com/support>

## Microchip Devices Code Protection Feature

---

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.

- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as “unbreakable.”

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip’s code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

## Legal Notice

---

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer’s risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

## Trademarks

---

The Microchip name and logo, the Microchip logo, AnyRate, AVR, AVR logo, AVR Freaks, BeaconThings, BitCloud, CryptoMemory, CryptoRF, dsPIC, FlashFlex, flexPWR, Heldo, JukeBlox, KeeLoq, KeeLoq logo, Klear, LANCheck, LINK MD, maXStylus, maXTouch, MediaLB, megaAVR, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, Prochip Designer, QTouch, RightTouch, SAM-BA, SpyNIC, SST, SST Logo, SuperFlash, tinyAVR, UNI/O, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

ClockWorks, The Embedded Control Solutions Company, EtherSynch, Hyper Speed Control, HyperLight Load, IntelliMOS, mTouch, Precision Edge, and Quiet-Wire are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, BodyCom, chipKIT, chipKIT logo, CodeGuard, CryptoAuthentication, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, EtherGREEN, In-Circuit Serial Programming, ICSP, Inter-Chip Connectivity, JitterBlocker, KlearNet, KlearNet logo, Mindi, MiWi, motorBench, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICKit, PICTail, PureSilicon, QMatrix, RightTouch logo, REAL ICE, Ripple Blocker, SAM-ICE, Serial Quad I/O, SMART-I.S., SQI, SuperSwitcher, SuperSwitcher II, Total Endurance, TSHARC, USBCheck, VariSense, ViewSpan, WiperLock, Wireless DNA, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

Silicon Storage Technology is a registered trademark of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2017, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

ISBN: 978-1-5224-1953-2

## Quality Management System Certified by DNV

---

### ISO/TS 16949

Microchip received ISO/TS-16949:2009 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC<sup>®</sup> MCUs and dsPIC<sup>®</sup> DSCs, KEELOQ<sup>®</sup> code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.

## Worldwide Sales and Service

AMERICAS	ASIA/PACIFIC	ASIA/PACIFIC	EUROPE
<p><b>Corporate Office</b> 2355 West Chandler Blvd. Chandler, AZ 85224-6199 Tel: 480-792-7200 Fax: 480-792-7277 Technical Support: <a href="http://www.microchip.com/support">http://www.microchip.com/support</a> Web Address: <a href="http://www.microchip.com">www.microchip.com</a></p> <p><b>Atlanta</b> Duluth, GA Tel: 678-957-9614 Fax: 678-957-1455</p> <p><b>Austin, TX</b> Tel: 512-257-3370</p> <p><b>Boston</b> Westborough, MA Tel: 774-760-0087 Fax: 774-760-0088</p> <p><b>Chicago</b> Itasca, IL Tel: 630-285-0071 Fax: 630-285-0075</p> <p><b>Dallas</b> Addison, TX Tel: 972-818-7423 Fax: 972-818-2924</p> <p><b>Detroit</b> Novi, MI Tel: 248-848-4000</p> <p><b>Houston, TX</b> Tel: 281-894-5983</p> <p><b>Indianapolis</b> Noblesville, IN Tel: 317-773-8323 Fax: 317-773-5453 Tel: 317-536-2380</p> <p><b>Los Angeles</b> Mission Viejo, CA Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800</p> <p><b>Raleigh, NC</b> Tel: 919-844-7510</p> <p><b>New York, NY</b> Tel: 631-435-6000</p> <p><b>San Jose, CA</b> Tel: 408-735-9110 Tel: 408-436-4270</p> <p><b>Canada - Toronto</b> Tel: 905-695-1980 Fax: 905-695-2078</p>	<p><b>Asia Pacific Office</b> Suites 3707-14, 37th Floor Tower 6, The Gateway Harbour City, Kowloon</p> <p><b>Hong Kong</b> Tel: 852-2943-5100 Fax: 852-2401-3431</p> <p><b>Australia - Sydney</b> Tel: 61-2-9868-6733 Fax: 61-2-9868-6755</p> <p><b>China - Beijing</b> Tel: 86-10-8569-7000 Fax: 86-10-8528-2104</p> <p><b>China - Chengdu</b> Tel: 86-28-8665-5511 Fax: 86-28-8665-7889</p> <p><b>China - Chongqing</b> Tel: 86-23-8980-9588 Fax: 86-23-8980-9500</p> <p><b>China - Dongguan</b> Tel: 86-769-8702-9880</p> <p><b>China - Guangzhou</b> Tel: 86-20-8755-8029</p> <p><b>China - Hangzhou</b> Tel: 86-571-8792-8115 Fax: 86-571-8792-8116</p> <p><b>China - Hong Kong SAR</b> Tel: 852-2943-5100 Fax: 852-2401-3431</p> <p><b>China - Nanjing</b> Tel: 86-25-8473-2460 Fax: 86-25-8473-2470</p> <p><b>China - Qingdao</b> Tel: 86-532-8502-7355 Fax: 86-532-8502-7205</p> <p><b>China - Shanghai</b> Tel: 86-21-3326-8000 Fax: 86-21-3326-8021</p> <p><b>China - Shenyang</b> Tel: 86-24-2334-2829 Fax: 86-24-2334-2393</p> <p><b>China - Shenzhen</b> Tel: 86-755-8864-2200 Fax: 86-755-8203-1760</p> <p><b>China - Wuhan</b> Tel: 86-27-5980-5300 Fax: 86-27-5980-5118</p> <p><b>China - Xian</b> Tel: 86-29-8833-7252 Fax: 86-29-8833-7256</p>	<p><b>China - Xiamen</b> Tel: 86-592-2388138 Fax: 86-592-2388130</p> <p><b>China - Zhuhai</b> Tel: 86-756-3210040 Fax: 86-756-3210049</p> <p><b>India - Bangalore</b> Tel: 91-80-3090-4444 Fax: 91-80-3090-4123</p> <p><b>India - New Delhi</b> Tel: 91-11-4160-8631 Fax: 91-11-4160-8632</p> <p><b>India - Pune</b> Tel: 91-20-3019-1500</p> <p><b>Japan - Osaka</b> Tel: 81-6-6152-7160 Fax: 81-6-6152-9310</p> <p><b>Japan - Tokyo</b> Tel: 81-3-6880-3770 Fax: 81-3-6880-3771</p> <p><b>Korea - Daegu</b> Tel: 82-53-744-4301 Fax: 82-53-744-4302</p> <p><b>Korea - Seoul</b> Tel: 82-2-554-7200 Fax: 82-2-558-5932 or 82-2-558-5934</p> <p><b>Malaysia - Kuala Lumpur</b> Tel: 60-3-6201-9857 Fax: 60-3-6201-9859</p> <p><b>Malaysia - Penang</b> Tel: 60-4-227-8870 Fax: 60-4-227-4068</p> <p><b>Philippines - Manila</b> Tel: 63-2-634-9065 Fax: 63-2-634-9069</p> <p><b>Singapore</b> Tel: 65-6334-8870 Fax: 65-6334-8850</p> <p><b>Taiwan - Hsin Chu</b> Tel: 886-3-5778-366 Fax: 886-3-5770-955</p> <p><b>Taiwan - Kaohsiung</b> Tel: 886-7-213-7830</p> <p><b>Taiwan - Taipei</b> Tel: 886-2-2508-8600 Fax: 886-2-2508-0102</p> <p><b>Thailand - Bangkok</b> Tel: 66-2-694-1351 Fax: 66-2-694-1350</p>	<p><b>Austria - Wels</b> Tel: 43-7242-2244-39 Fax: 43-7242-2244-393</p> <p><b>Denmark - Copenhagen</b> Tel: 45-4450-2828 Fax: 45-4485-2829</p> <p><b>Finland - Espoo</b> Tel: 358-9-4520-820</p> <p><b>France - Paris</b> Tel: 33-1-69-53-63-20 Fax: 33-1-69-30-90-79</p> <p><b>France - Saint Cloud</b> Tel: 33-1-30-60-70-00</p> <p><b>Germany - Garching</b> Tel: 49-8931-9700</p> <p><b>Germany - Haan</b> Tel: 49-2129-3766400</p> <p><b>Germany - Heilbronn</b> Tel: 49-7131-67-3636</p> <p><b>Germany - Karlsruhe</b> Tel: 49-721-625370</p> <p><b>Germany - Munich</b> Tel: 49-89-627-144-0 Fax: 49-89-627-144-44</p> <p><b>Germany - Rosenheim</b> Tel: 49-8031-354-560</p> <p><b>Israel - Ra'anana</b> Tel: 972-9-744-7705</p> <p><b>Italy - Milan</b> Tel: 39-0331-742611 Fax: 39-0331-466781</p> <p><b>Italy - Padova</b> Tel: 39-049-7625286</p> <p><b>Netherlands - Druenen</b> Tel: 31-416-690399 Fax: 31-416-690340</p> <p><b>Norway - Trondheim</b> Tel: 47-7289-7561</p> <p><b>Poland - Warsaw</b> Tel: 48-22-3325737</p> <p><b>Romania - Bucharest</b> Tel: 40-21-407-87-50</p> <p><b>Spain - Madrid</b> Tel: 34-91-708-08-90 Fax: 34-91-708-08-91</p> <p><b>Sweden - Gothenburg</b> Tel: 46-31-704-60-40</p> <p><b>Sweden - Stockholm</b> Tel: 46-8-5090-4654</p> <p><b>UK - Wokingham</b> Tel: 44-118-921-5800 Fax: 44-118-921-5820</p>