

AXIAL LED, GULL WINGS LEADS,

AXIAL LED, GULL WINGS LEADS,

AXIAL LED, GULL WINGS LEADS,

OUR NAMY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE. PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.

SSL-LXA228SYC-TR11

THE INFORMATION CONTINUED IN THIS DOCUMENT IS THE PROPERTY OF LUMEX NO. EXCEPT AS SPECIFICALLY AUTHORIZED IN WRITING BY LUMEX INC., THE HOLDER OF THIS DOCUMENT SHALL KEEP ALL INFORMATION CONTINUED HEREIN CONFIDENTIAL AND SHALL PROTECT SAME IN WHOLE OR IN PART FROM DISCLOSURE AND DISSEMBLION TO ALL THIRD PARTIES.

290 E. HELEN ROAD PALATINE, IL 60067—6976 PHONE: +1.847.359.2790 US WEB: www.lumex.com TW WEB: www.lumex.com.tw

DRAWN BY: CHECKED BY:

APPROVED BY:

: DATE: 11.15.06 PAGE: 1 OF 1 SCALE: N/A

JC

## **Mouser Electronics**

**Authorized Distributor** 

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

Lumex:

SSL-LXA228SYC-TR11