

Desoldering Stations

Electronically Controlled Desoldering Stations

Order No. 005 33 683 99 Model WR 3000M **Description**

Same as model WR 3000M (left side) but with desoldering iron DXV 80





Hot air nozzles: see page 136-141 Soldering tips: see page 87 / 88 Desoldering nozzles: see page 123 Spare parts: see www.weller.eu





consists of:	
005 33 666 99	WR 3M
005 27 116 99	HAP 200
005 15 152 99	WDH 30
005 15 153 99	WDH 40
005 13 180 99	DXV 80
005 29 180 99	WP 80
005 15 161 99	WDH 10T
005 29 184 99	WVP

Accessories: 005 87 388 50 005 13 120 99 Power unit 230 V Hot air iron 200 W / 24 V Safety rest for HAP 200 Safety rest for DXV 80 Inline desoldering iron 80 W, 24 V Soldering iron 80 W with soldering tip LT B Safety rest with Stop+Go function for WP 80 Vacuum pick up

Adaptor for footswitch Food switch 1-step

USB cable and software