

# Product Change Notification



Product Group: SFERNICE /Oct 20, 2006/PCN-SF / FL 046- 2005 Rev 0

## TRIMMERS: TSM4 / TS63 / T63

**DESCRIPTION OF CHANGE:** Sealing becomes BLACK (was blue) due to raw material obsolescence.

**CLASSIFICATION OF CHANGE:** Form Fit Function (pictures attached)

**REASON FOR CHANGE:** Raw Material Obsolescence

**EXPECTED INFLUENCE ON QUALITY/RELIABILITY/PERFORMANCE:** No effect.

**PRODUCT CATEGORY:** Trimmers

**PART NUMBERS/SERIES/FAMILIES AFFECTED:** TSM4XX , TS63XXX, T63XXX, TS6XXX & T6XXX,

**VISHAY BRAND(s):** Vishay Sfernice

**TIME SCHEDULE:**

Last Time Buy Date: n/a application production D/C > 0701

Last Time Shipment Date : n/a

**SAMPLE AVAILABILITY:** Immediate

**PRODUCT IDENTIFICATION:** Date Code, color

**QUALIFICATION DATA:** Available on request

**This PCN is considered approved, without further notification, unless we receive specific customer concerns before 31/12/06 or as specified by contract.**


**ISSUED BY:** Frederic Lovera / Marketing Mgr. Frederic.lovera@vishay.com

**For further information, please contact your regional Vishay office.**

**CONTACT INFORMATION:**

**See your standard customer service**

**T63** Before After



**TSM4** Before After



**TS63** Before After

