

Product Change Notification

Current Date: 02-Mar-2022

TE Connectivity

Product Change Notification: P-22-022251 PCN Date: 28-FEB-22

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

1001230 R580S 0.25MM*25MM F

Description of Changes

Additional manufacturing location for plating component PN 704586-5. Current supplier is TE Kurim, CZ and new supplier is an outside supplier, Leading Tachnologies, in USA. No change to the manufacturing location of the finished goods/ sellable part numbers and no change to current shipping point.

| Reason for Changes: | | | | | | |
|--|--|--|--|--|--|--|
| Product improvement.Increase available global capacity for the plated component. | | | | | | |
| Estimated Dates: | | | | | | |
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): | | | | | |
| | 24-AUG-2022 | | | | | |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): | | | | | |
| | No Mixed Shipments | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per | Customer | Alias Part | Substitute Part | Substitute Alias Part | Description Of |
|----------------------|-----------------------|----------|------------|-----------------|-----------------------|----------------|
| | PCN | Drawing | Number(s) | Number | Number(s) | Difference |
| 1241380-3 | NO | | | | | |
| <u>1557773-1</u> | NO | | | | | |
| <u> 1557773-2</u> | NO | | | | | |
| <u> 1557774-1</u> | NO | | | | | |
| <u> 1557774-3</u> | NO | | | | | |
| <u> 1557774-4</u> | NO | | | | | |
| <u> 1557800-2</u> | NO | | | | | |
| <u>1557800-3</u> | NO | | | | | |
| <u> 1557800-4</u> | NO | | | | | |
| 1557800-5 | NO | | | | | |
| <u>1557801-1</u> | NO | | | | | |
| <u> 1557801-2</u> | NO | | | | | |
| 1557801-3 | NO | | | | | |
| <u>1557801-4</u> | NO | | | | | |
| <u>1557873-1</u> | NO | | | | | |
| <u>1557874-1</u> | NO | | | | | |
| <u> 1557915-1</u> | NO | | | | | |
| <u> 1557921-1</u> | NO | | | | | |
| <u> 1557922-1</u> | NO | | | | | |
| 1557949-1 | NO | | | | | |
| <u>2306039-1</u> | NO | | | | | |
| 2306271-1 | NO | | | | | |
| 2321027-1 | NO | | | | | |
| <u>2321028-1</u> | NO | | | | | |
| 2396926-1 | NO | | | | | |
| 5-1557773- <u>1</u> | NO | | | | | |
| <u>5-1557773-2</u> | NO | | | | | |
| 5-1557773- <u>3</u> | NO | | | | | |
| 5-1557773 <i>-</i> 5 | NO | | | | | |
| 5- <u>1557773-7</u> | NO | | | | | |
| <u>5-1557773-8</u> | NO | | | | | |
| 5-1557774-1 | NO | | | | | |
| 5-1557774-3 | NO | | | | | |
| 5-1557774-4 | NO | | | | | |

| Part Number | Part Discontinued per PCN | Customer Drawing | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|--------------------|---------------------------|---------------------|-------------------------|---------------------------|------------------------------------|------------------------------|
| <u>5-1557774-5</u> | NO | | | | | |
| 5-1557774-7 | NO | | | | | |
| <u>5-1557802-1</u> | NO | | | | | |
| 5-1557803-1 | NO | | | | | |
| 5-1557909-1 | NO | | | | | |
| 5-1557910-1 | NO | | | | | |
| 5-1557910-2 | NO | | | | | |
| 5-1557911-1 | NO | | | | | |
| 5-1557915-1 | NO | | | | | |
| 5-1557921-1 | NO | | | | | |
| 5-1557922-1 | NO | | | | | |
| 5-1557986-1 | NO | | | | | |
| 5-1557987-1 | NO | | | | | |
| <u>5-2304580-1</u> | NO | | | | | |