


**INTRODUCTION**

The detail shown within this instruction sheet gives guidance for the assembly of the chosen cable to connector. (Refer to the table for the applicable connector part numbers covered by this document).  
The assembly instructions are in sketch form, which show the sequence of how to assemble.  
The sketches are relevant for both jacks and plugs. For clarity, only one type of connector is shown.  
Cable preparation to be undertaken in accordance with normal safety precautions using cable stripping tools that are commercially available.

**PART NUMBERS, CABLE PREPARATION AND TOOLING TABLE**




VERSION 2

connector P/N	Cable Strip Dimensions			Hand Tool Part No.	Die Set Part No.
	A	B	C		
1-1337606-0	6.5	1.3	2.0	Not required	Not required
1-1478007-0	6.0	1.3	2.5	Not required	Not required
1-1478008-0	6.0	1.3	2.5	Not required	Not required


CABLE TO CONNECTOR DIAGRAM FOLLOWS ON NEXT PAGE.

<u>REVISION RECORDS</u>					
A	RELEASE FOR PRODUCTION	R.GOODALL	F.W-KING	F.W-KING	12 NOV 2001
REVISION	DESCRIPTION	DRAWN BY	CHECKED BY	APPROVED BY	DATE

CAP                      MAIN BODY                      SLEEVE                      WASHER                      NUT




STEP 1





INSERT  
→

STEP 2



INSERT  
→


STEP 3



↓ PRESS

SOLDER

STEP 4



SCREW TIGHTEN

STEP 5

