

Тороидальные трансформаторы с двойной вторичной обмоткой • серия 55 xxx - P1S2



Мощность [VA]	Номер заказа	Монтаж*	Первич.напряж. [V]	Вторич.напряж. [V]	Вторич.ток [A]	Напряж. х.х. U _o [V]	Предохранитель (вторич.) [A]	Размеры (р*в) / Масса . [mm / kg]
15	55 100 - P1S2	S	230	2 x 12	0,625	2 x 13,89	0,630	62 x 32 / 0,31
	55 300 - P1S2	H						
	55 101 - P1S2	S						
	55 301 - P1S2	H						
	55 102 - P1S2	S						
	55 302 - P1S2	H						
	55 103 - P1S2	S						
55 303 - P1S2	H							
30	55 110 - P1S2	S	230	2 x 12	1,250	2 x 14,19	1,250	74 x 34 / 0,44
	55 310 - P1S2	H						
	55 111 - P1S2	S						
	55 311 - P1S2	H						
	55 112 - P1S2	S						
	55 312 - P1S2	H						
	55 113 - P1S2	S						
55 313 - P1S2	H							
50	55 120 - P1S2	S	230	2 x 12	2,083	2 x 13,71	2,000	84 x 34 / 0,63
	55 320 - P1S2	H						
	55 121 - P1S2	S						
	55 321 - P1S2	H						
	55 122 - P1S2	S						
	55 322 - P1S2	H						
	55 123 - P1S2	S						
	55 323 - P1S2	H						
55 129 - P1S2	S							
55 329 - P1S2	H							
80	55 130 - P1S2	S	230	2 x 12	3,333	2 x 13,60	3,150	95 x 36 / 0,87
	55 330 - P1S2	H						
	55 131 - P1S2	S						
	55 331 - P1S2	H						
	55 132 - P1S2	S						
	55 332 - P1S2	H						
	55 133 - P1S2	S						
	55 333 - P1S2	H						
55 139 - P1S2	S							
55 339 - P1S2	H							
120	55 140 - P1S2	S	230	2 x 12	5,000	2 x 13,42	5,000	96 x 47 / 1,20
	55 340 - P1S2	H						
	55 141 - P1S2	S						
	55 341 - P1S2	H						
	55 142 - P1S2	S						
	55 342 - P1S2	H						
	55 143 - P1S2	S						
	55 343 - P1S2	H						
	55 149 - P1S2	S						
55 349 - P1S2	H							
160	55 150 - P1S2	S	230	2 x 12	6,667	2 x 13,26	6,300	110 x 46 / 1,50
	55 350 - P1S2	H						
	55 151 - P1S2	S						
	55 351 - P1S2	H						
	55 152 - P1S2	S						
	55 352 - P1S2	H						
	55 153 - P1S2	S						
	55 353 - P1S2	H						
	55 154 - P1S2	S						
	55 354 - P1S2	H						
55 159 - P1S2	S							
55 359 - P1S2	H							

Мощность [VA]	Номер заказа	Монтаж*	Первич.напряж. [V]	Вторич.напряж. [V]	Вторич.ток [A]	Напряж. х.х. U ₀ [V]	Предохранитель (вторич.) [A]	Размеры (р*в) / Масса [mm / kg]
225	55 160 - P1S2	S	230	2 x 12	9,375	2 x 13,14	10,000	118 x 50 / 1,9
	55 360 - P1S2	H						
	55 161 - P1S2	S						
	55 361 - P1S2	H						
	55 162 - P1S2	S						
	55 362 - P1S2	H						
	55 163 - P1S2	S						
	55 363 - P1S2	H						
	55 164 - P1S2	S						
	55 364 - P1S2	H						
300	55 173 - P1S2	S	230	2 x 25	6,000	2 x 26,85	6,300	118 x 60 / 2,4
	55 373 - P1S2	H						
	55 174 - P1S2	S						
	55 374 - P1S2	H						
	55 175 - P1S2	S						
	55 375 - P1S2	H						
	55 179 - P1S2	S						
	55 379 - P1S2	H						
500	55 183 - P1S2	S	230	2 x 25	10,000	2 x 26,71	10,000	140 x 62 / 3,5
	55 383 - P1S2	H						
	55 184 - P1S2	S						
	55 384 - P1S2	H						
	55 185 - P1S2	S						
	55 385 - P1S2	H						
	55 186 - P1S2	S						
	55 386 - P1S2	H						
	55 187 - P1S2	S						
	55 387 - P1S2	H						
	55 188 - P1S2	S						
	55 388 - P1S2	H						
625	55 196 - P1S2	S	230	2 x 40	7,813	2 x 42,32	8,000	140 x 75 / 4,4
	55 396 - P1S2	H						
	55 197 - P1S2	S						
	55 397 - P1S2	H						
	55 198 - P1S2	S						
	55 398 - P1S2	H						
	55 199 - P1S2	S						
	55 399 - P1S2	H						
800	55 206 - P1S2	S	230	2 x 40	10,000	2 x 42,38	10,000	165 x 65 / 5,3
	55 406 - P1S2	H						
	55 207 - P1S2	S						
	55 407 - P1S2	H						
	55 208 - P1S2	S						
	55 408 - P1S2	H						
	55 209 - P1S2	S						
55 409 - P1S2	H							
1000	55 216 - P1S2	S	230	2 x 40	12,500	2 x 41,76	12,500	165 x 75 / 6,4
	55 416 - P1S2	H						
	55 217 - P1S2	S						
	55 417 - P1S2	H						
	55 218 - P1S2	S						
	55 418 - P1S2	H						
	55 219 - P1S2	S						
55 419 - P1S2	H							

*) Монтаж:

S - стандартный монтажный набор

H - залитый центр со сквозным отверстием