LIQUIDPROOF PROTECTION

Vital 117

DESCRIPTION AND GENERAL PROPERTIES

- Material Natural latex
- Length (cm) 30,5
- Thickness (mm) 0.35
- Wrist Straight cuff
- Colour/Color Blue
- Interior finish Flocked
- Exterior finish Embossed texture
- Size / EAN 6 7 8 9 10
- Packaging 1 pair/bag 10 pairs/bag 100 pairs/carton



PERFORMANCE RESULTS

Certification category 3





Legends MECHANICAL LOW CHEMICAL MICRO-ORGANISMS RADIOACTIVE PROTECTION CONTAMINATION HAZARDS EN 374 EN 388 EN 421 EN 374 PERFORMANCE LEVELS 0-4 0-5 0-4 0-4 Puncture resistance SPECIFIC CHEMICAL COLD HAZARDS Tear resistance PROTECTION EN 511 ^LBlade cut resistance EN 374 PERFORMANCE LEVELS Abrasion resistance Letter Chemical 0-4 0-4 0 or 1 Code product Water permeability HEAT A Methanol -Contact cold resistance AND FIRE В Acetone Convective cold resistance EN 407 С Acetonitrile D Dichloromethane PERFORMANCE LEVELS Е Carbon Disulfide 0-4 0-4 0-4 0-4 0-4 0-4 F Toluene Resistance to large quantities of molten metal G Diethylamine -Resistance to small drops of molten metal Н Tetrahydrofurane -Radiant heat resistant Ethyl acetate I Convective heat resistance .1 n-Heptane Sodium hydroxide 40% -Contact heat resistance Κ Sulphuric acid 96% -Burning behaviour L

For more details: **www.mapa-pro.com**



MAPA SPONTEX PROFESSIONNEL - Défense Ouest - 420, rue d'Estienne d'Orves - 92705 Colombes Cedex - FRANCE Tel: +33 (0)1 49 64 22 00 - Fax: +33 (0)1 49 64 24 29

DESCRIPTION AND GENERAL PROPERTIES

- Excellent dexterity from the suppleness of natural latex
- Good resistance
- Comfortable cotton flock-lining

MAIN FIELDS OF USE

Mechanical industry

- Assembly of small, oil and grease free parts
- Local Authorities (Cleaning)
- Handling household detergents

INSTRUCTIONS FOR USE

Instructions for use

- It is recommended to check that the gloves are suitable for the intended use, because the conditions of use at workplace may differ from the «CE»-type tests.
- It is not recommended for persons sensitised to natural latex, dithiocarbamates and thiazoles to use these gloves.
- Put the gloves on dry, clean hands.
- Do not use the gloves in contact with a chemical for a duration in excess of the measured breakthrough time. Refer to the website www. mapa-pro.com or contact the Technical Customer Service MAPA PROFESSIONNEL (stc.mapaspontex@mapaspontex.fr) in order to know this breakthrough time. Use 2 pairs alternatively when in long duration contact with a solvent.
- Turn the cuff end down in order to prevent a hazardous chemical from dripping onto the arm.
- Inspect the gloves for cracks or snags before reusing them.

Storage conditions

Store the gloves in their original packaging protected from direct sunlight, far from heat sources or electric equipment. Laundering conditions

Before taking off the gloves, clean them as appropriate :

- in use with a solvent (alcohol, etc...) : rub over with a dry cloth
- in use with detergents, acids or alkalies : thoroughly rinse the gloves under running water, and rub over with a dry cloth

Caution : using the gloves or submitting them to another cleaning or laundering process can alter their performance levels.

Drying conditions

Ensure the inside of the gloves is dry before putting them on again.

LEGISLATION

This product is not classified as hazardous according to the directive 1999/45/EC of the European Parliament and of the Council. This product does not contain any substances of very high concern according to the regulation n° 1907/2006 of the European Parliament and of the Council (REACH).

• CE-Type Examination Certificate

0075/014/162/09/09/0406 Ext 01/09/09

• Issued by the notified body nr

0075

C.T.C - 4, rue Hermann Frenkel - 69367 Lyon cedex 07 - France

• Quality assurance certificat

0334 Asqual 14 rue des Reculettes -F-75013 PARIS

