


(3.4)

USING EITHER OF THE SPANNER WRENCHES SHOWN ABOVE, GUIDE SETS MAY BE REMOVED AND REPOSITIONED IN ANY OF THE 64 POLARIZING POSITIONS. REFER TO PAGE WA-18 FOR POLARIZATION CHART.

CAUTION: WHEN POLARIZED POSITIONS ARE CHANGED, APPLY LOCTITE 242 ® TO THREADS.


IF SPANNER NUTS ARE DIFFICULT TO REMOVE DUE TO HARDENED LOCTITE ®, APPLY HEAT (300° F) TO NUT AREA FOR ONE HOUR AND REPEAT REMOVAL OPERATION.




THE 1/4" DRIVE SPANNER WRENCH ABOVE IS DESIGNED FOR USE IN TORQUE WRENCHES

### Accessories

#### Insertion & Removal Tools






### Accessories

Crimp Tools & Positioners

TC1652 - CRIMP TOOL REF M22520/2-01 TP1653 - POSITIONER REF M22520/2-06





.135/.145 ---

TOOL SELECTION TABLE		
CONTACT	TOOL NO.	POSITIONER
WTK2222P		TP1985
WTK2222S	TC1652	TP1653
WTK2220S657		TP2435
WTK2220P657		TP13784

- 5/16" HEX

# **Mouser Electronics**

**Authorized Distributor** 

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

## AirBorn:

TN1680 TN4612 TP2435 TR1610 TR1883 TN21243 TP13784