

GLOVE SIZING CHART

Ordering the right size is the best way to assure that gloves are comfortable. One way to determine the size needed is to use a dressmaker's cloth tape to measure around the hand. Measure above the thumb and below the fingers. The circumference of the hand (rounded to the nearest half inch; 1 inch = 2,54 cm) is numerically equal to the worker's average glove size.

Measuring the hands in this way will not account for all possible variations in hand size. Some workers, for example, may have long fingers, while others will have short fingers. Workers may find gloves that are one-half or even a full size larger or smaller than the measured hand size fit more comfortably.

SIZE #	XS	S	M	L	XL	XXL
Size	6	7	8	9	10	11

ALL GLOVES WITH A CUFF ARE COLOUR CODED FOR SIZE IDENTIFICATION AS BELOW.

SIZE	6	7	8	9	10	11
Overedge Colour*	Purple	Red	Yellow	Brown	Black	Light Blue
* Except for Vantage® proFood®	Brown	Green	White	Red	Blue	

