

## PeakTech® 5160 PROD-ID: P 5160

[BACK](#)

### Temperature-/Humidity Meter

This newly developed instrument measures the current humidity, as well as the current air temperature over a fixed sensor for fast and accurate evaluation of the measurement results.

The easy to read LCD display is equipped with an automatic backlight, which activates itself in low brightness areas by a photodiode.

In addition to the precise measurement function, this device also offers a data hold function.

By the handy and robust design, this instrument is especially suitable for the daily use in the construction sector, as well as the assessment of the climate state of living rooms and greenhouses.

- 3 -digits 10 mm LCD display (max. 999)
- Automatic backlight illumination
- Relative Humidity measurement
- Air temperature display in °C or °F
- Fast acting sensors
- Rugged and compact housing design
- Data-Hold function
- Accessories: Battery and manual



#### MANUAL

[PeakTech\\_5160\\_04-2017B.pdf \(614.4 kB\)](#)

#### PICTURES

[5160\\_F.jpg \(220.1 kB\)](#)

[5160\\_L.jpg \(221.0 kB\)](#)

[5160\\_R.jpg \(226.0 kB\)](#)

Relative Humidity	10% - 99% ; 0.1 ; +/- 3%
Air Temperature °C	- 10°C ~ +50°C ; 0.1 ; +/- 2°C
Air Temperature °F	14°F ~ 122°F ; 0.1 ; +/- 3.6°F
Sampling rate	2 x per second
Operating voltage	9 V-battery
Dimensions (WxHxD)	55 x 145 x 35 mm
Weight	120 g
EAN-13	4250569403217

