

| Part # | Package | P _D (W) | I _C (A) | V _{CEO} (V) | V _{CBO} (V) | h _{FE} |
|----------|----------|--------------------|--------------------|----------------------|----------------------|-----------------|
| BUT11 | TO-220 | 100 | 5 | 400 | 850 | 10-35 |
| BUT11A | TO-220 | 100 | 5 | 450 | 1000 | 10-35 |
| BUT11AF | TO-220F | 20 | 5 | 450 | 1000 | 10-35 |
| BUT11AF | TO-220Fa | 40 | 5 | 450 | 1000 | 10-35 |
| BUT11AFI | TO-220F | 35 | 5 | 450 | 1000 | 10-35 |
| BUT11AI | TO-220 | 100 | 5 | 450 | 1000 | 14-35 |
| BUT11APX | TO-220F | 32 | 5 | 450 | 1000 | 14-35 |
| BUT11AX | TO-220F | 32 | 5 | 450 | 1000 | 10-35 |
| BUT11F | TO-220Fa | 20 | 5 | 400 | 850 | 10-35 |
| BUT11FI | TO-220F | 20 | 5 | 400 | 850 | 10-35 |
| BUT12 | TO-220 | 100 | 8 | 400 | 850 | 10-35 |
| BUT12A | TO-220 | 100 | 8 | 450 | 1000 | 10-35 |
| BUT12AF | TO-220Fa | 23 | 8 | 450 | 1000 | 10-35 |
| BUT12AX | TO-220F | 23 | 8 | 450 | 1000 | 10-35 |
| BUT12F | TO-220Fa | 23 | 8 | 400 | 850 | 10-35 |
| BUT131 | TO-220 | 80 | 5 | 450 | 850 | 5- |
| BUT131A | TO-220 | 80 | 5 | 500 | 1000 | 5- |
| BUT131H | TO-220 | 80 | 5 | 450 | 850 | 7- |
| BUT18 | TO-220 | 110 | 6 | 400 | 800 | 10-35 |
| BUT18A | TO-220 | 110 | 6 | 450 | 1000 | 10-35 |
| BUT18AF | TO-220Fa | 33 | 6 | 450 | 1000 | 10-35 |
| BUT18F | TO-220Fa | 33 | 6 | 400 | 800 | 10-35 |
| BUT211 | TO-220 | 100 | 5 | 400 | 850 | 18-25 |
| BUT211X | TO-220F | 32 | 5 | 400 | 850 | 18-25 |
| BUT21B | TO-220 | 100 | 5 | 400 | 750 | 25(TYP) |
| BUT21BF | TO-220Fa | 20 | 5 | 400 | 750 | 25(TYP) |
| BUT21C | TO-220 | 100 | 5 | 450 | 850 | 25(TYP) |
| BUT21CF | TO-220Fa | 20 | 5 | 450 | 850 | 25(TYP) |
| BUT22B | TO-220 | 125 | 8 | 400 | 750 | |
| BUT22BF | TO-220Fa | 23 | 8 | 400 | 750 | |
| BUT22C | TO-220 | 125 | 8 | 450 | 850 | |
| BUT22CF | TO-220Fa | 23 | 8 | 450 | 850 | |
| BUT46 | TO-220 | 75 | 5 | 400 | 850 | |
| BUT46A | TO-220 | 75 | 5 | 450 | 1000 | |
| BUT50P | TO-3PN | 100 | 8 | 500 | 850 | |
| BUT54 | TO-220 | 100 | 8 | 430 | 800 | |
| BUT55 | TO-220 | 105 | 12 | 400 | 400 | 100- |
| BUT56 | TO-220 | 100 | 8 | 400 | 800 | |
| BUT56A | TO-220 | 100 | 8 | 450 | 1000 | |

| | | | | | | |
|---------|----------|-----|----|-----|------|--|
| BUT56AF | TO-220Fa | 23 | 8 | 450 | 1000 | |
| BUT76 | TO-220 | 100 | 10 | 400 | 850 | |
| BUT76A | TO-220 | 100 | 10 | 450 | 1000 | |
| BUT76AF | TO-220Fa | 23 | 10 | 450 | 1000 | |
| BUT93 | TO-220 | 55 | 4 | 350 | 600 | |
| BUT81AF | TO-220Fa | 33 | 4 | 450 | 1000 | |