



## NOTES:

- 1. OPERATION
  - 1. GENTLY LIFT LATCH AT SIDE OF CONNECTOR.
  - 2. SWING COVER OFF OF CONTACTS.
  - 3. SLIDE THE FLEX TAPE INTO THE CONNECTOR PLACING THE EDGE OF THE FLEX TAPE UNDER 2 HOLD DOWN TABS.
  - 4. FOLD OVER THE COVER AND PRESS IN PLACE UNTIL THE LATCH IS FULLY ENGAGED.
- 2. LIMIT CURRENT TO A MAXIMUM OF 5 AMPS.

JKL PART NO.: ZCH-143HD-8 I

			METRIC (+)	DIMENSIONS ARE IN mm (INCHES) TOLERANCE UNLESS OTHERWISE SPECIFIED		COMPONENTS CORPORATION					
			THIRD ANGLE PROJECTION	1 PL +/- 2 PL +/- ANGLE +/-	REF.	TITLE	NO SOLDER 8mm FLEX TAPE INPUT CONNECTOR				
Α	ADD SIDE VIEW RELEASE & CANCEL PL-1409-03	8/20/15 10/10/14	I WENGSTROM	APPV'D BY L.R.	DATE 8/20/15	SIZE <b>A</b>	55335	DRAWING NO.	ZCH-143HD	)-8I	
REV. NO.	DESCRIPTION/ECO NUMBER	APPV'D DATE	- CAD DRAWING - MANUAL REVISIONS NOT PERMITTED			SCALE		DATE 10/10/14	REVISION DATE 8/20/15	NO. A	SHEET 1 OF 1

## **Mouser Electronics**

**Authorized Distributor** 

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

 $\frac{\text{JKL Components}}{\text{ZCH-143HD-8I}}:$