



The Best Relaytion



Cradle Relay Accessories



Sockets with hand solder terminals

Size I



Approx. weight 3.5 g

Sockets with PCB terminals

Size I



Approx. weight 4.5 g

Size II



Approx. weight 4.5 g

Size II




Approx. weight 5.5 g

Size III



Approx. weight 5.5 g

Size III



Approx. weight 6.5 g




Sockets with hand solder terminals


Sockets with PCB terminals


Dimension drawing (in mm)


with hold-down spring for cradle relays N, S and P

















Socket	Size I	Size II	Size III
Dimension a	26.6	32.5	38



Ordering Code

Version	Size	Ordering code	Tyco Part Number
Sockets			
for printed circuit mounting,	I	V23154-Z1001	0-1393824-1
terminals silver-plated	II	V23154-Z1002	9-1393809-1
with earth terminal	III	V23154-Z1028	1-1393824-0
for solder terminals,	I	V23154-Z1005	0-1393824-4
hand solder terminals, silver-plated	II	V23154-Z1006	0-1393824-5
	II	V23154-Z1015	0-1393824-8
Hold-down springs			
for cradle relays N, S and P	I	V23154-Z1021	0-1393824-5
	II	V23154-Z1022	0-1393827-2
	III	V23154-Z1034	0-1393760-2
for cradle relay W	I	V23154-Z1023	0-1393827-3
	II	V23154-Z1024	0-1393760-1

Gold plated terminals on request

General Data


Terminal material	CuSn8 FB 390 plated with min. 3 $\mu{\rm m}$ silver or min. 1 $\mu{\rm m}$ gold	
Socket material with solder terminals	Phenolformaldehyde - type 31 (DIN 7708, part 2)	
Socket material with PCB terminals	Makrolon (polycarbonate)	
Maximum continous current at 70° C	5 A	



Minimum spacings between sockets


Dimension drawing (in mm)

with hold-down spring for cradle relays N, S and P




Socket	Dimension c
Size I	27
Size II	33
Size III	39

for cradle relay P Relays oriented in the same direction



Socket	Dimension b	Dimension c
Size I	27	42
Size II	33	48
Size III	39	54

Relays oriented inversely to each other




When mounting cradle relay P consideration should be given to magnetic fields. Strong DC magnetic fields, possibly caused by adjacent relays, and large iron masses are the most common causes of interference. Experience has shown that under normal operating conditions the minimum spacings specified for cradle relay P are sufficient to prevent cross interference.



Mounting hole layout for cradle relays and sockets with hand solder terminals


Dimension drawing (in mm)

with hold-down spring for cradle relays N, S and P



*) This hole is omitted when the mounting hole layout is intended for the socket.

Fixing of the socket




Direct mounting of relays without socket requires a fixing nut M2.5 DIN 934-m6AU. Ordering code: D00934-A0025-S001



Mounting hole layot for sockets with PCB terminals

Basic grid 2.5 mm according to EN 60097

Dimension drawing (in mm)



View onto the terminals

- M = Earth terminal
- a) Hole for mechanical armature actuation, if required
- b) Hole for the socket mounting with screw M1.6

Fixing of the socket

