


IN Your Innovation

Product Change Notification (PCN)

PhotoMOS[®], MOSFET Drivers and AQH

Change of safety standards certification authority

Date: December 1st, 2023
T-1507



Reason for change	We will change the safety standards certification authority from VDE to BSI and obtain IEC/EN62368-1.	
Series affected	PhotoMOS [®] , MOSFET drivers and AQH in SOP, DIP, SIL and PD packages	
Part no. affected	See next page Part number, specification and price remain unchanged.	
Replacement recommendation	Not needed, no technical changes of the relays.	
Changes: Safety standards No. Safet standards certification authority	Before change IEC/EN62368-1 (Equipment Standards) VDE	After change Same as left (no change) BSI
Change schedule	From July 24 shipments onwards	

IN Your Innovation

Part numbers affected

Product type	Package	Part No.
PhotoMOS®	SOP4	AQY***S
	SOP6	AQV***S
	SOP8	AQW***S
	DIP4	AQY***
	DIP6	AQV***
	DIP8	AQW***
	PD4	AQY*7*
	SIL4	AQZ*0*
	SIL4	AQZ19*
MOSFET Drivers	SOP4	APV*121S
	DIP6	APV*122
Solid State Relay	DIP8	AQH*2*3